



- All stock under one crane way. 1 crane feeds multiple shearlines
 All fabrication under one crane way. Crane has short travel to load all trucks
 Straight bundles close to trucks

Crane has short travel to load all trucks

- Bent bar bundles load next
 Stirrup ties load last
- Stage several trucks in loading area

- Easy to expand just add to length
- Material is parallel to crane